



Built Up Vehicle Inspection Report

V627/1

For completion by Applicant

Name and Address

Present Registration Mark

UQR 339K

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 Telephone Number \_\_\_\_\_  
 Daytime Telephone Number \_\_\_\_\_

Make DOON  
 Model LWB BUGGY  
 Colour YELLOW  
 Taxation Class HISTORIC VEHICLE  
 Year of Manufacture 1972  
 Currently Licensed Yes  No

Major Components (delete as appropriate)	Serial/ID number	Origin (Registration Mark or New)	Make of Vehicle Component	Receipts * Yes/No
Chassis/ <del>Body/Shell</del>	1122657694	UQR 339K	VOLKSWAGEN	YES
Axles	NONE	UQR 339K	VOLKSWAGEN	YES
Transmission	NONE	UQR 339K	VOLKSWAGEN	YES
Steering Assembly	NONE	UQR 339K	VOLKSWAGEN	YES
Engine	AB552316	UQR 339K	VOLKSWAGEN	YES
Suspension (front and back)	NONE	UQR 339K	VOLKSWAGEN	YES

Motorcycles				
Frame				
Forks				
Wheels				
Engine / Gearbox				

A. Original parts not used (state below how disposed)

Body and wings scrapped.

\*Receipts for replacement parts must be produced to support applications

B. Any other information / Additional Documents produced

(Retention of original Registration Mark may be considered but only if the details prior to alteration are held at DVLA.)

Signature \_\_\_\_\_ Date 30<sup>th</sup> October 2005 →

The Particulars given above are believed to be correct to the best of my knowledge.



An executive agency of the  
Department for Transport

3/04